INDIVIDUAL PROPERTY/DISTRICT MARYLAND HISTORICAL TRUST INTERNAL NR-ELIGIBILITY REVIEW FORM

Property/District Name: Robert H. Felix, Jr. Farm	Survey Number:	G-IV-A-266
Project: US 219/Oakland Vicinity Improvement Project	Agency: MSHA	
Site visit by MHT Staff: No Yes Name	Dat	e
Eligibility recommended Eligibility not recommended X		
Criteria: A B C D Considerations: A	B C D _	E F G None
Justification for decision: (Use continuation sheet if necessdary and attach map)		
The Robert H. Felix Jr. Farm, with its main dwelling built <i>circa</i> 1900 and its agric century, documents the agricultural landscape surrounding the county seat of Oakl centuries. Agriculture was the predominant economic activity outside of Oakland comprised about 50 percent of the county's land mass in 1880, and more than 60 p raised potatoes, orchard products, oats, corn, buckwheat, wheat, rye, and barley as	and in the late nineto in the late nineteent ercent by 1910. Far	eenth and early twentieth h century, as farmland ms of this period typically
Research has not identified any associations with the lives of persons significant to contributed significantly to broad patterns of the area's historical development. The distinctive type, period, or method of construction, nor does it represent the work of represent a significant and distinguishable entity whose components may lack individed and is not likely to yield significant information important in history or present as the contributed and is not likely to yield significant information important in history or present as the contributed significant information important in history or present as the contributed significant information important in history or present as the contributed significant information important in history or present as the contributed significant information important in history or present as the contributed significant information important in history or present as the contributed significant information important in history or present as the contributed significant information important in history or present as the contributed significant information important in history or present as the contributed significant information important in history or present as the contributed significant information important in history or present as the contributed significant information important in history or present as the contributed significant information important in history or present as the contributed significant information important in history or present as the contributed significant information in the contributed significant in the contributed significant in th	ne architecture does not a master, possess vidual distinction.	not represent a particularly high artistic values, or
Document on the property/district is presented in: Historic Structures Inventory a	and Determination of	f Eligibility Report
(KCI/MSHA 1997)		
Prepared by: Gabrielle M. Lanier/KCI Technologies, Inc.		-1-10-
Bloth		7/1/18
Reviewer, Office of Preservation Services	/	/ Date
NR program concurrence: yes no not applicable		1,
Reviewer, NR program	<u> </u>	Date

Robert H. Felix, Jr. Farm Complex G-IV-A-266 3783 Pleasant Valley Road Oakland Vicinity Circa 1900-1910 Private

This farm complex includes a farmhouse, a springhouse, a tractor shed, a garage, and three barns. The house is a two-story, three-by-two-bay, gable-roofed, L-plan frame dwelling with three one-story shed-roofed additions, an open sided hip-roofed front porch that extends the full width of the front elevation, and a small one-story gable-roofed frame rear entry. It is built with a stone foundation, fiberboard and asbestos-shingled walls, and an asphalt-shingled gable roof with an interior brick chimney. Windows are a mixture of single and tripled one-over-one and two-over-two, double-hung sash with wooden trim. Most door openings contain wood or wood and glass doors with wooden surrounds.

Outbuildings on the property include a modern tractor shed, a stone springhouse with a working spring, a modern aluminum garage, a gable-roofed, gable-fronted frame barn, a large gambrel-roofed, gable-fronted, two-story frame bank barn with an attached concrete block milkhouse, and a reworked, partially embanked, one-story frame barn now used as a stable. The house faces south-southeast and occupies a mostly open, relatively flat piece of land on Pleasant Valley Road about two-and-one-half miles southeast of Oakland.

The Robert H. Felix Jr. Farm, with its main dwelling built *circa* 1900 and its agricultural buildings constructed in the early twentieth century, documents the agricultural landscape surrounding the county seat of Oakland in the late nineteenth and early twentieth centuries.

Inventory No. G-IV-A-266

Maryland Historical Trust Maryland Inventory of Historic Properties Form

1. Name of P	roperty	(indicate preferred nan	ne)		
historic	···		-		
other	Robe	rt H. Felix, Jr.			
2. Location					
street & number	3782 P	leasant Valley Road		not for public	cation
city, town	Oaklaı	nd		X vicinity	
county	Garret	t			
3. Owner of F	Property	(give names and mai	ling addresses of all owners)		
name	Rober	t H. Felix, Jr.			
street & number	3782 P	leasant Valley Road		telephone	301-334-2467
city, town	Oaklan	d		state and zip code	MD 21550-9202
4. Location o	f Legal [Description			
courthouse, registry of	deeds, etc. (Garrett County Courthou	se	tax map and parcel	85-10-13
city, town	(Oakland		liber and folio	572/202
5. Primary Lo	cation o	of Additional [Data		
Determined Ineligi	urce in Local H e for the Natior ble for the Nation S/HAER				
6. Classificat	ion				
district	wnership public < private both	Current Function X agriculture commerce/trade defense X domestic education funerary government health care industry	landscape recreation/ culture religion social transportation work in progress unknown vacant/not in use other:	Resource Count Contributing Nonco 6 2 0 0 0 0 0 0 6 2 Number of Contributing Nonco Contr	buildings sites structures objects Total uting Resources

7. Descrip	AUOH	Inventory No. G-IV-A-266
Condition		
excellent	deteriorated	
good	ruins	
<u>X</u> fair	altered	

7 Description

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

This farm complex includes a farmhouse, a springhouse, a tractor shed, a garage, and three barns. The house is a two-story, three-by-two-bay, gable-roofed, L-plan frame dwelling with three one-story shed-roofed additions, an open sided hip-roofed front porch that extends the full width of the front elevation, and a small one-story gable-roofed frame rear entry. The house faces south-southeast and stands on a mostly open, relatively flat section of land on Pleasant Valley Road about two-and-one-half miles southeast of Oakland.

The house is built on a coursed and roughly dressed stone foundation that encloses a full cellar. The building is presently sheathed in a mixture of fiberboard and asbestos shingles. An asphalt-shingled gable roof finished with a plain flat verge, exposed rafter feet, and a wooden eave tops the building; the roof is further embellished with curved sawn partial comice returns. Lozenge-shaped fixed sash windows light the attic of the main block near the roof peak. A single interior brick chimney with a corbeled top rises from the center of the roof at the ridge line. The house is presently painted yellow with white trim.

Windows consist of a mixture of single and tripled one-over-one and two-over-two, double-hung sash finished with a mixture of molded and plain flat wooden surrounds. A single octagonal fixed-sash window lights the second story on the southwest elevation. and several three-light fixed sash windows light the cellar level. The front door opening, which is located near the southernmost corner of the house, contains a wooden door lit by a single pane of glass; the door opening is finished with a flat wooden surround. The covered rear entry, which is topped with a corrugated metal roof and clad in fiberboard walling, is fitted with a solid particleboard door. Two additional doors provide access to the interior: one, which is located on the southwest elevation, is constructed entirely of plywood. The other, located on the northeast side of the smallest one-story shed-roofed addition, contains a more finished wooden door lit by a two-light glass upper section.

The open front porch consists of a stone foundation, a wooden deck, three battered wooden porch posts, and an asphalt-shingled hipped roof. The rear porch consists simply of an open concrete stoop on brick piers, a set of concrete steps, and an iron handrail. One of the shed-roofed additions is located on the northeast side of the house, nestled in the right angle of the L of the building's main block. This addition is sheathed with plywood, topped with an asphalt-shingled shed roof, and accessed by several concrete steps. The other two shed-roofed additions are built end-to-end and extend along the southwest side of the house. Both are sheathed in asbestos shingles and topped with a continuous asphalt-shingled shed roof.

Several outbuildings stand on the property. An open-sided, one-story, gable-roofed tractor or equipment storage shed built on four-by-four wooden posts stands just off of the eastern corner of the house. This open shed is covered with a corrugated aluminum roof. A gable-roofed stone springhouse stands near the house's westernmost corner. The springhouse is covered with a standing seam metal roof that is further embellished with scrolled metal roof cresting at each gable peak. A working spring still runs through the building. A gable-roofed, gable entry, one-bay, one-story garage stands east of the house; this building is completely clad and roofed with corrugated aluminum. A gable-roofed, gable-fronted barn topped with a corrugated metal roof stands just north of the house; this building is sheathed in a combination of weatherboards and vertical boards and accessed by a set of sliding wooden doors in the gable.

Further to the west stands a large gambrel-roofed, gable-fronted, two-story frame bank barn. This building is clad in a mixture of board-and-batten and weatherboard walling. Access to the interior is provided by several doors of varying sizes on the ground floor level as well as a set of double wooden doors at the loft level. A roof extension or cat's head projects over these doors and protects a beam hoist and hay track extension. Several rectangular louvers located on the long walls ventilate the barn's interior. An earthen embankment or ramp built against the northern elevation leads to the barn's upper level. According to the owner, this barn was built in the first decade of the twentieth century. A gable-roofed one-story concrete block milkhouse, which is also located on the north side of the barn, is partially embanked. The milkhouse is topped with a corrugated metal roof; its gables are clad in board-and-batten siding and its interior is lit by two-over-two, double-hung sash windows.

A reworked, partially embanked, one-story frame barn built on a stone and rusticated concrete block foundation stands near the northeast corner of this large gambrel-roofed barn. An earth and stone embankment built against the north wall of this building leads to its upper level. This building is topped with a rolled asphalt roof and lit primarily by tripled sets of two-over-two, double-hung sash windows with flat wooden surrounds. An open-sided, one-story, shed-roofed frame leanto topped with a corrugated metal roof is built on the barn's south elevation. This building was used most recently to house pigs, but has since been reclaimed for use as a stable.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. G-IV-A-266

Name	
Continuation Sheet	
Number 7 Page 1	

A long driveway, which runs diagonally between the house and garage, extends westward toward the gambrel-roofed barn. Because the present property owner raises horses and a variety of other livestock, the house and outbuildings are surrounded by a series of corrals, several of which are enclosed with electrified wire fences. The house is in fair condition and is currently occupied.

8. Signific	ance		Inventory No. G-IV-A-266	
Period1600-16991700-17991800-1899X 1900-19992000-	Areas of Significance X agriculture archeology architecture art commerce communications community planning conservation	Check and justify below	 health/medicine industry invention landscape architecture law literature maritime history military 	performing arts philosophy politics/government religion science social history transportation other:
Specific dates	Circa 1900-1910	Builder/Arch	itect Unknown	
Evaluation for:				
X National Register Maryland Register not evaluated				

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance reports, complete evaluation on a DOE Form - see manual).

The Robert H. Felix Jr. Farm, with its main dwelling built *circa* 1900 and its agricultural buildings constructed in the early twentieth century, documents the agricultural landscape surrounding the county seat of Oakland in the late nineteenth and early twentieth centuries. Agriculture was the predominant economic activity outside of Oakland in the late nineteenth century, as farmland comprised about 50 percent of the county's land mass in 1880, and more than 60 percent by 1910. Farms of this period typically raised potatoes, orchard products, oats, com, buckwheat, wheat, rye, and barley as well as cattle, sheep, swine, and horses.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Historic Function(s) and Use(s):

Known Design Source:

Inventory No. G-IV-A-266

Name Continuation Sheet Number 8 Page 1			
HISTORIC CONTEXT:			
MARYLAND COMPREHENSIVE PRESERVATION PLAN DATA			
Geographic Organization:	Western Maryland		
Chronological/Developmental Period(s):	Industrial / Urban Dominance A.D. 1870-1930		
Historic Period Theme(s):	Agriculture		
Resource Type:			
Category:	Buildings		
Historic Environment:	Rural		

Dwelling and agricultural buildings

None

9. Major Bibliographical References

Inventory No. G-1V-A-266

(See Continuation Sheet)

10. Geographical Data

Acreage of property 53.23 acres

Acreage surveyed 53.23 acres

Quadrangle name Qakland, MD-WVA

WVA Quadrangle scale 1:24000

Verbal boundary description and justification

Parcel 13, Map 85, Grid 10

11. Form Prepared By

name/title	Gabrielle M. Lanier, Architectural Historian		
organization	KCl Technologies, Inc.	date	3/18/97
street & number	10 North Park Drive	telephone	410-316-7857
city or town	Hunt Valley	state and zip code MD 21030-1888	

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

retum to:


Maryland Historical Trust DHCD/DHCP 100 Community Place Crownsville, MD 21032 410-514-7600


Maryland Historical Trust Maryland Inventory of Historic Properties Form

Name Continuation Sheet		
Number 9 Page 1		

BIBLIOGRAPHY

- Garrett County Historical Society. v. d. Vertical Files. On file at the Garrett County Historical Society, Oakland, MD.
- Lacoste, Kenneth C., Robert D. Wall, and Robert C. Sonderman. An Archeological Study of the Western Maryland Coal Region: The Historic Resources. Maryland Geological Survey. Report on file at the Maryland Historical Trust, Crownsville, MD. 1989.
- Roberts, Charles S. West End, Cumberland to Grafton, 1848-1991. Barnard, Roberts & Co., Inc., Baltimore, MD. 1991.
- Schlosnagle, Stephen, and The Garrett County Bicentennial Committee. Garrett County, A History of Maryland's Tableland. McClain Printing Company, Parsons, West Virginia. Second Edition. 1989.
- Ware, Donna M., and Mark R. Edwards. Final Report of the Coal Region Historic Sites Survey, Volume I: Methodology and Management Plan. Maryland Historical Trust. Report on file at the Maryland Historical Trust, Crownsville, MD. 1984.
- Ware, Donna M., Orlando Ridout V and Geoffrey B. Henry. Final Report of the Coal Region Historic Sites Survey, Volume II: Historical, Architectural, and Industrial Overviews. Maryland Historical Trust. Report on file at the Maryland Historical Trust, Crownsville, MD. 1984.
- Ware, Donna M., Orlando Ridout V, Geoffrey B. Henry and Mark R. Edwards. *Green Glades & Sooty Gob Piles*. Maryland Historical & Cultural Publications, Crownsville, MD. 1991.
- Weeks, Thekla Fundenberg. Oakland Centennial History, 1849-1949. The Sincell Printing Company, Oakland, MD. 1949.







G-II.A.266

GARRETT COINTY, MD

STUART DIXON

1 31 97

MD SHPO

S ELEVATION LOOKING N

0F 5



G-TV-A-266

GARRETT COUNTY, MD STUART DIXON 1/31/97 MD SHPO E ELEVATION LOOKING W

2 = 5



G-IV-A-266

GARRETI COUNTY, MD STUART DIXIN 1/31/97 MD SHPO NECEUATION GOOKING S

3 OF 5



G-II-A-266

STUART DIXON

1/31/97

MD SHPO

SELEVATION GOORING N

4 0 5



G-IV. A.266

CARRETT COUNTY MD STUART DIXON S ELEVATION LOOPING N